


Corretto assemblaggio del gruppo 52Q00106  
Correct fitting order 52Q00106



52Q00452R

56T00185

52Q00522

34E00337

56T00183SW2

Bush spare part:  
56T00215 theoretical separation 3,5mm  
or  
28A00587S theoretical separation 3mm

56T00187

52Q00508R

34E00314R (X4)

52Q00423R

56T00234


34E00401R (X3)

52Q00329R


Super Elf G2 HD+  
Plasma coated sector

P/N 56F00729

Document number :23E00949  
Drawing number : 024844d01



Corretto ordine di assemblaggio gruppo 56T00214  
Correct fitting order 56T00214 group



Power cable spare part p/n 05R01270

**Super Elf G2 HD+**  
**Plasma coated sector**  
P/N 56F00729

Document number :23E00949  
Drawing number : 024844d01